








A (mm)	B (mm)	C (mm)	D (mm)
540, 557	1744	1772	1775-1780
540, 557	1369	1397	1400-1405
540, 557	1197	1224	1225-1231
540, 557	997	1024	1025-1031
540, 557	847	875	878-883




- A: 5x (Screws)
- B: 12x (Screws)
- C: 4x (Washers)
- D: 1x (Bracket)
- E: 1x (Bracket)
- F: 2x (Bracket)
- G: 2x (Cap)
- H: 4x (Bracket)
- I: 4x (Bracket)
- J: 1x (Bracket)
- K: 1x (Panel)
- L: 3x (Bracket)
- M: 1x (Trim)
- N: 1x (Bracket)
- O: 1x (Bracket)
- P: 2x (Cap)
- R: 1x (Bracket)
- S: 1x (Cable)
- T: 1x (Bracket)
- U: 1x (Trim)



1




3




A

1


1x




4




2







4x











5






B






3

P 2x




1




4

T 1x



2




C →

C


1

C 4x H 4x




2

S 1x



3


M 1x



4







D 1x E 1x





5

D 1x E 1x F 2x








8





9



10





11




12

B 5x




13




14

○ 1x




16


Ⓜ 1x







15




17







22



1

N 1x



E

